#### Gunter, Jason

From:

Seabourne, Rocky <rseabourne@doerun.com>

Sent:

Thursday, November 19, 2015 9:21 AM

To:

'brandon.wiles@dnr.mo.gov'; Gunter, Jason; Montgomery, Michael; Neaville, Chris; Ty Morris;

Yingling, Mark

Subject:

Emailing: Elvins-Rivermines Monthly Progress Report October

Attachments:

Elvins-Rivermines Monthly Progress Report October.pdf; 9 - Remediation Air Report -

September 2015.pdf; 2015-10-07 RM NPDES Pace Lab Report.pdf

Your message is ready to be sent with the following file or link attachments:

Elvins-Rivermines Monthly Progress Report October

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

\*

This message is intended solely for the designated recipient and may contain confidential, privileged or proprietary information. If you have received it in error, please notify the sender immediately and delete the original and any copy or printout. Please note that any views or opinions presented in this e-mail are solely those of the author and do not necessarily represent those of The Doe Run Company. Finally, the recipient should check this message and any attachments for the presence of viruses or malware. The Doe Run Company accepts no liability for any loss or damage caused through the transmission of this e-mail.

07CR 40504723
Superfund
0102 11/19/15

52



SOUTHEAST MISSOURI MINING AND MILLING DIVISION P.O. Box 500 Viburnum, MO 65566

Rocky Seabourne
General Supervisor Land & Remediation
rseabourne@doerun.com

November 12, 2015

Mr. Jason Gunter Remedial Project Manager U.S. Environmental Protection Agency Region 7 – Superfund Branch 11201 Renner Blvd. Lenexa, KS 66219

RE: The Doe Run Company - Elvins/Rivermines Mine Tailings Site Monthly Progress Report

Dear Mr. Gunter:

As required by Article VI, Section 56 of the Unilateral Administrative Order (UAO) (CERCLA-07-2005-0169) for the referenced project and on behalf of The Doe Run Company, the progress report for the period of October 1, 2015 through October 31, 2015 is enclosed. If you have any questions or comments, please feel free to contact me at 573-244-8136.

Sincerely,

Rocky Seabourne

General Supervisor Land & Remediation c:Mark Yingling – TDRC (electronic only)

Chris Neaville - TDRC (electronic only)

Michael Montgomery - TDRC (electronic only)

Brandon Wiles - MDNR HWP

Ty Morris - Barr Engineering

#### Elvins/Rivermines Mine Tailings Site Park Hills, Missouri Removal Action - Monthly Progress Report Period: October 1, 2015 – October 31, 2015

- 1. Actions performed or Completed This Period:
  - a. Work continued on the development of the Post-Removal Site Control Plan for the site.
  - b. Given the nature of the work remaining at the site, The Doe Run Company would like to request a reduction in the frequency of the progress reports to quarterly.
  - c. Monthly water samples were taken during the removal action activities. These samples have been continued since the completion of the removal action activities. The analytical results, which have been included in the progress reports, have shown little variation. As a result Doe Run would like to request a reduction in the frequency of the sampling to quarterly.
  - d. Started construction on Storm Water Management Plan.

e.

- 2. Analytical Data and Results Received This Period:
  - a. During this period, water samples were collected from just upstream of Old Missouri Highway 32, as well as from upstream and downstream of the confluence of the site discharge with Flat River. The analytical results for this event are included with this progress report.
  - During this period, the ambient air monitoring samples for September were processed and attached.
- 3. Developments Anticipated and Work Schedule for Next Period:
  - a. Complete the water sampling activities.
  - b. Complete air monitoring activities as described in the Removal Action Work Plan.
  - c. Continue developing the Post-Removal Site Control Plan.
- 4. Issues or Problems Encountered and the Resolution:
  - a. None.

# **Monthly Ambient Air Monitoring Report**

The Doe Run Company
Old Lead Belt Sites:
Federal, Rivermines, National, and Leadwood

September-2015



SUITE 300 1801 PARK 270 DRIVE ST. LOUIS, MO 63146

#### **Federal Site**

#### Sample Results for September-2015

	St. Ioe (I	Ballfields)	Big Ri	iver#4		reatment ant
	TSP	Lead	TSP	Lead	TSP	Lead
Sample Date	ug/m3	ug/m3	ug/m3	ug/m3	ug/m3	ug/m3
9/1/15	44	0.007	invalid	invalid	33	0.007
9/2/15	48	0.007	35	0.020	20	0.007
9/3/15	36	0.007	46	0.028	24	0.007
9/4/15	44	0.007	31	0.014	27	0.014
9/8/15	30	0.028	22	0.021	22	0.028
9/9/15	18	0.007	invalid	invalid	invalid	invalid
9/10/15	16	0.007	14	0.020	invalid	invalid
9/11/15	20	0.007	14	0.007	14	0.007
9/14/15	24	0.007	invalid	invalid	17	0.007
9/15/15	27	0.007	24	0.021	23	0.014
9/16/15	34	0.007	30	0.014	24	0.007
9/17/15	35	0.014	36	0.007	33	0.007
9/18/15	28	0.007	16	0.007	22	0.007
9/21/15	20	0.007	47	0.007	16	0.014
9/22/15	22	0.014	30	0.033	21	0.014
9/23/15	29	0.042	35	0.021	33	0.041
9/24/15	27	0.021	28	0.013	12	0.007
9/25/15	31	0.014	invalid	invalid	invalid	invalid
9/28/15	13	0.007	17	0.000	13	0.000
9/29/15	21	0.007	19	0.007	22	0.007
9/30/15	22	0.007	19	0.007	21	0.014

Monthly Avg. TSP	28	27	22
Monthly Avg. Pb	0.011	0.014	0.012
Aug-15	0.012	0.012	0.021
Jul-15	0.007	0.008	0.014
Rolling 3-Month	0.010	0.011	0.016

Three month rolling average must be less than 0.15 ug/m3

	Big Ri	ver QA
	TSP	Lead
Sample Date	ug/m3	ug/m3
9/1/15	31	0.007
9/3/15	30	0.028
9/8/15	21	0.014
9/10/15	11	0.021
9/15/15	23	0.020
9/17/15	35	0.007
9/22/15	invalid	invalid
9/24/15	invalid	invalid
9/29/15	17	0.007

#### **Notes**

#### **Rivermines**

#### Sample Results for September-2015

	Big Ri			s South #1		s North #2	Rivermine	
	TSP	Lead	TSP	Lead	TSP	Lead	TSP	Lead
Sample Date	ug/m3	ug/m3	ug/m3	ug/m3	ug/m3	ug/m3	ug/m3	ug/m3
9/1/15	invalid	invalid	34	0.014	32	0.036	33	0.007
9/2/15	35	0.020	invalid	invalid	38	0.128	20	0.007
9/3/15	46	0.028	26	0.014	27	0.043	24	0.007
9/4/15	31	0.014	invalid	invalid	27	0.021	27	0.014
9/8/15	22	0.021	invalid	invalid	19	0.043	22	0.028
9/9/15	invalid	invalid	invalid	invalid	17	0.043	invalid	invalid
9/10/15	14	0.020	11	0.027	17	0.049	invalid	invalid
9/11/15	14	0.007	invalid	invalid	13	0.007	14	0.007
9/14/15	invalid	invalid	18	0.007	19	0.014	17	0.007
9/15/15	24	0.021	22	0.007	21	0.014	23	0.014
9/16/15	30	0.014	23	0.007	25	0.014	24	0.007
9/17/15	36	0.007	33	0.007	31	0.034	33	0.007
9/18/15	16	0.007	invalid	invalid	20	0.007	22	0.007
9/21/15	47	0.007	48	0.152	18	0.034	16	0.014
9/22/15	30	0.033	28	0.034	22	0.013	21	0.014
9/23/15	35	0.021	50	0.132	30	0.055	33	0.041
9/24/15	28	0.013	51	0.081	24	0.007	12	0.007
9/25/15	invalid	invalid	invalid	invalid	29	0.007	invalid	invalid
9/28/15	17	0.000	29	0.034	8	0.007	13	0.000
9/29/15	19	0.007	58	0.288	20	0.007	22	0.007
9/30/15	19	0.007	76	0.277	19	0.007	21	0.014

Monthly Avg. TSP	27	36	23	22
Monthly Avg. Pb	0.014	0.077	0.028	0.012
Aug-15	0.012	0.068	0.012	0.021
Jul-15		0.053	0.013	0.014
Rolling 3-Month	0.011	0.066	0.018	0.016

Three month rolling average must be less than 0.15 ug/m3

	Big Ri	ver QA
	TSP	Lead
Sample Date	ug/m3	ug/m3
9/1/15	31	0.007
9/3/15	30	0.028
9/8/15	21	0.014
9/10/15	11	0.021
9/15/15	23	0.020
9/17/15	35	0.007
9/22/15	invalid	invalid
9/24/15	invalid	invalid
9/29/15	17	0.007

#### **Notes**

**Federal Site** 

Sample Results for September-2015

	St. Joe (Ballfields)	Big River#4	Water Treatment
Sample Date	<b>PM10</b> (ug/m3)	<b>PM10</b> (ug/m3)	<b>PM10</b> (ug/m3)
9/1/15	invalid	invalid	invalid
9/3/15	30	27	22
9/6/15	invalid	58	invalid
9/9/15	invalid	invalid	invalid
9/12/15	invalid	invalid	invalid
9/15/15	21	invalid	invalid
9/18/15	invalid	invalid	invalid
9/21/15	3	14	invalid
9/24/15	invalid	invalid	invalid
9/27/15	invalid	invalid	invalid
9/30/15	13	12	invalid

Compliance with NAAQS is less than 150 ug/m3

Monthly Avg. PM10 17	28	22
----------------------	----	----

	Big River QA
Sample Date	<b>PM10</b> (ug/m3)
9/3/15	invalid
9/9/15	24
9/15/15	invalid
9/21/15	9
9/27/15	13

#### Notes:

#### **Rivermines**

Sample Results for September-2015

	Big River #4	Rivermines South #1	Rivermines North #2	Rivermines East #3
Sample Date	<b>PM10</b> (ug/m3)	PM10 (ug/m3)	<b>PM10</b> (ug/m3)	<b>PM10</b> (ug/m3)
9/1/15	invalid	invalid	invalid	invalid
9/3/15	27	35	25	22
9/6/15	58	25	23	invalid
9/9/15	invalid	invalid	invalid	invalid
9/12/15	invalid	invalid	invalid	invalid
9/15/15	invalid	invalid	invalid	invalid
9/18/15	invalid	invalid	invalid	invalid
9/21/15	14	15	invalid	invalid
9/24/15	invalid	invalid	invalid	invalid
9/27/15	invalid	invalid	invalid	invalid
9/30/15	12	invalid	invalid	invalid

Compliance with NAAQS is less than 150 ug/m3

Monthly Avg. PM10	28	25	24	22

	Big River QA
Sample Date	<b>PM10</b> (ug/m3)
9/3/15	invalid
9/9/15	24
9/15/15	invalid
9/21/15	9
9/27/15	13

#### Notes:

# Meterological Data - Old Lead Belt September-2015

24hr average

Date Date	Wind Speed (MPH)	Wind Direction	Sigma-Theta	Temperature (C)	Air Pressure (mmHg)	Rain (Inches)	Power Supply (Volts)
01-Sep-15	2.38	201.8	24.24	25.8	747	0	13.18
02-Sep-15	1.581	211	25.21	25.33	746	0	13.17
03-Sep-15	1.642	214.3	26.13	26.04	745	0	13.17
04-Sep-15	1.54	203.1	28.05	26.09	745	0	13.16
05-Sep-15	1.925	186	24.59	25.97	746	0	13.16
06-Sep-15	2.223	189.4	28.84	26.7	745	0	13.15
07-Sep-15	2.412	187	24.92	25.33	745	0	13.18
08-Sep-15	2.855	217	28.2	25.71	743	0.03	13.18
09-Sep-15	1.494	88.8	32.75	22.62	744	0.25	13.21
10-Sep-15	1.768	214.6	35.86	21.7	743	0	13.21
11-Sep-15	3.82	330.8	25.18	18.59	744	0.14	13.27
12-Sep-15	4.372	317.2	24.18	13.57	746	0	13.33
13-Sep-15	2.366	216	35.82	15.14	746	0	13.34
14-Sep-15	3.852	185.3	23.76	18.91	748	0	13.29
15-Sep-15	4.382	179.3	22.71	20.5	749	0	13.25
16-Sep-15	3.933	172.3	23.03	21.8	749	0	13.24
17-Sep-15	5.497	201.5	24.59	25.55	745	0	13.2
18-Sep-15	4.348	218.4	27.75	27.33	741	0	13.17
19-Sep-15	4.484	310.8	25.27	19.73	745	0.01	13.21
20-Sep-15	1.675	161.2	27.69	14.13	748	0	13.33
21-Sep-15	1.861	174.7	33.66	16.26	747	0	13.31
22-Sep-15	1.708	161.6	34.34	18.67	748	0	13.28
23-Sep-15	1.87	161.3	28.98	19.28	749	0	13.26
24-Sep-15	1.884	192.5	32.91	19.06	748	0	13.27
25-Sep-15	2.224	251.6	25.61	18.85	748	0	13.27
26-Sep-15	1.957	95	24.01	16.54	748	0	13.32
27-Sep-15	1.188	125.6	25.8	19.4	745	0.3	13.3
28-Sep-15	1.644	189	27.72	20.59	744	0.1	13.27
29-Sep-15	1.864	356.6	24.95	20.22	744	0.3	13.28
30-Sep-15	4.791	2.608	24.33	15.92	747	0	13.32



August 28, 2015

Mr. Greg Henson Chemist The Doe Run Company 881 Main Street Herculaneum, Missouri 63048

RE: Park Hill Monitoring Network 3rd Quarter 2015 Lead/PM10 Samplers and Meteorological System Performance Audit Report.

Dear Mr. Henson,

Please find enclosed the worksheets detailing the Lead/PM10 sampler's one-point flow verifications and meteorological sensors accuracy checks that were recently performed on the Doe Run Park Hills Monitoring Network. A copy of the current certifications for the audit devices that were used has also been enclosed.

All of the verifications and checks were found to be within expected guidelines.

After reviewing the enclosed information, please feel free to call with any comments or questions. Thank you for your business.

Sincerely,

John A. Kunkel

Inquest Environmental, Inc.

# **PM10 Sampler Verifications**



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor	John Kunk	el	
Operator	The Doe Run Company	Transfer Orifice	1882		
Location	Park Hills Network	Slope (Qa)	1.04094		
Station	Big River	Intercept (Qa)	-0.00876		
Sampler	#4 Primary PM10	Temperature	28.3	_°C	301.5 °K
Flow Controller	P2952	Station Pressure	30.08	"Hg	764.0 mmHg

20-44 - 192 - 249 - 24 - 24-44 - 14-5 - 24	Carrier St. Hills of C	150 AF 15 152 AF	Flow Ra	ate Audit	3. A. E. Y. A.	TAMBLE D	EME IN
Transfer Orifice			Sampler			Flow Rate	Accontable
Manometer "H₂O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Percent Difference	Acceptable Range
3.30	1.105	25.40	47.44	0.938	1.139	3.08	± 7%

HIV DON'T	Sampler Operating Flow Rate							
Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Design % Difference	Acceptable Range		
25.60	47.81	0.937	1.138	1.103	-2.39	± 10%		

#### Calculations:

Pressure mmHg (Pf) - ("H2O/13.6) \* 25.4

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Flow Rate Percent Difference- (Sampler Flow-Orifice Flow)/Orifice Flow\*100

Corrected Flow Rate - Operating Flow\*((100-Percent Difference)/100)



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor	John Kunk	el		
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	Big River	Intercept (Qa)	-0.00876			
Sampler	#4 QA PM10	Temperature	28.3	_°C	301.5	°K
Flow Controller	P1019	Station Pressure	30.08	"Hg	764.0	mmHg

HEN SKA	Flow Rate Audit								
Transfe	r Orifice		Sam	npler		Flow Rate	Assantable		
Manometer "H <sub>2</sub> O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Percent Difference	Acceptable Range		
3.40	1.121	27.10	50.61	0.934	1.147	2.32	± 7%		

100 St 10	Sampler Operating Flow Rate							
Manometer "H₂O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Design % Difference	Acceptable Range		
27.10	50.61	0.934	1.147	1.120	-0.88	± 10%		

#### Calculations:

Pressure mmHg (Pf) - ("H<sub>2</sub>O/13.6) \* 25.4

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Flow Rate Percent Difference- (Sampler Flow-Orifice Flow)/Orifice Flow\*100

Corrected Flow Rate - Operating Flow\*((100-Percent Difference)/100)



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	January 20, 2015	Auditor	John Kunke	el		
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	St Joe Park	Intercept (Qa)	-0.00876			
Sampler	#4 PM10	Temperature	31.8	_°C	305.0 °K	
Flow Controller	P4353	Station Pressure	30.08	_"Hg	764.0 mr	nHg

Flow Rate Audit								
Transfe	ansfer Orifice Sampler		Sampler		Flow Rate	Assantable		
Manometer "H <sub>2</sub> O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Percent Difference	Acceptable Range	
3.10	1.077	24.90	46.50	0.939	1.136	5.48	± 7%	

Sampler Operating Flow Rate							
Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Design % Difference	Acceptable Range	
24.90	46.50	0.939	1.136	1.074	-4.96	± 10%	

#### Calculations:

Pressure mmHg (Pf) - ("H2O/13.6) \* 25.4

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Flow Rate Percent Difference- (Sampler Flow-Orifice Flow)/Orifice Flow\*100

Corrected Flow Rate - Operating Flow\*((100-Percent Difference)/100)



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor	John Kunke	el		
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	Rivermines (Wtr Plnt)	Intercept (Qa)	-0.00876			
Sampler	#3 PM10	Temperature	31.8	_°C	305.0	°K
Controller	P2951	Station Pressure	30.08	_"Hg	764.0	mmHg

Flow Rate Audit								
Transfe	r Orifice		Sam	pler		Flow Rate	Acceptable	
Manometer "H <sub>2</sub> O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Percent Difference	Range	
3.10	1.077	25.50	47.63	0.938	1.147	6.50	± 7%	

Sampler Operating Flow Rate								
Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Design % Difference	Acceptable Range		
25.60	47.81	0.937	1.146	1.072	-5.13	± 10%		

#### Calculations:

Flow

Pressure mmHg (Pf) - ("H<sub>2</sub>O/13.6) \* 25.4

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Flow Rate Percent Difference- (Sampler Flow-Orifice Flow)/Orifice Flow\*100

Corrected Flow Rate - Operating Flow\*((100-Percent Difference)/100)



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor	John Kunke	el		
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	Rivermines (Quarry)	Intercept (Qa)	-0.00876			
Sampler	#1 PM10	Temperature	31.8	°C	305.0	°K
Flow Controller	P4601	Station Pressure	30.08	"Hg	764.0	mmHg

Flow Rate Audit									
Transfe	r Orifice		Sam	pler		Flow Rate	Assontable		
Manometer "H <sub>2</sub> O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Percent Difference	Acceptable Range		
3.30	1.111	24.60	45.94	0.940	1.121	0.90	± 7%		

Sampler Operating Flow Rate							
Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Design % Difference	Acceptable Range	
24.50	45.76	0.940	1.121	1.111	-1.68	± 10%	

#### Calculations:

Pressure mmHg (Pf) - (" $H_2O/13.6$ ) \* 25.4

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Flow Rate Percent Difference- (Sampler Flow-Orifice Flow)/Orifice Flow\*100

Corrected Flow Rate - Operating Flow\*((100-Percent Difference)/100)



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor	John Kunk	el		
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	Rivermines (Above Quarry)	Intercept (Qa)	-0.00876			
Sampler	#2 PM10	Temperature	31.8	°C	305.0	°K
Flow Controller	P4507	Station Pressure	30.08	_"Hg	764.0	mmHg

Flow Rate Audit									
Transfe	r Orifice		Sampler			Flow Rate	Acceptable		
Manometer "H <sub>2</sub> O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Percent Difference	Range		
3.30	1.111	26.00	48.56	0.936	1.136	2.25	± 7%		

Sampler Operating Flow Rate								
Manometer "H₂O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Design % Difference	Acceptable Range		
26.10	48.75	0.936	1.136	1.110	-1.77	± 10%		

#### Calculations:

Pressure mmHg (Pf) -("H<sub>2</sub>O/13.6) \* 25.4

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Flow Rate Percent Difference- (Sampler Flow-Orifice Flow)/Orifice Flow\*100

Corrected Flow Rate - Operating Flow\*((100-Percent Difference)/100)

# Lead/TSP Sampler Verifications



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor	John Kunke	el		
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	Big River Primary	Intercept (Qa)	-0.00876			
Sampler	#4 TSP	Temperature	28.3	_°C	301.5	°K
Flow Controller	P4557	Station Pressure	30.08	_"Hg	764.0	mmHg

Flow Rate Audit									
Transfe	r Orifice		Sam	pler		Calibantina	A		
Manometer "H <sub>2</sub> O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Calibration Error %	Acceptable Range		
3.85	1.193	23.90	44.65	0.942	1.239	3.86	± 7%		

Sampler Operating Flow Rate							
Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m <sup>3</sup> /min	Corrected Flow Rate	Acceptable Range		
23.00	42.97	0.944	1.242	1.194	1.10 - 1.70		

#### Calculations:

Pressure mmHg (Pf) - "H2O \* 1.86832

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Calibration Error - (Sampler Flow-Orifice Flow)/Orifice Flow\*100



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor	John Kunke	el .		
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	Big River QA	Intercept (Qa)	-0.00876			
Sampler	#4 TSP	Temperature	28.3	_°C	301.5	°K
Flow Controller	P4558	Station Pressure	30.08	"Hg	764.0	mmHg

abe will	Flow Rate Audit									
Transfe	r Orifice		Sampler			Calibration	Assentable			
Manometer "H₂O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Calibration Error %	Acceptable Range			
3.90	1.200	23.10	43.16	0.944	1.237	3.08	± 7%			

Sampler Operating Flow Rate							
Manometer "H₂O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Acceptable Range		
23.10	43.16	0.944	1.237	1.199	1.10 - 1.70		

#### Calculations:

Pressure mmHg (Pf) - "H2O \* 1.86832

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Calibration Error - (Sampler Flow-Orifice Flow)/Orifice Flow\*100



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor	John Kunke	el		
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	St Joe Park	Intercept (Qa)	-0.00876			
Sampler	#4 TSP	Temperature	31.8	_°C	305.0	°K
Flow Controller	P6792	Station Pressure	30.08	_"Hg	764.0	mmHg

N-331340	Flow Rate Audit								
Transfe	r Orifice	Sampler			Calibantian	Assautable			
Manometer "H <sub>2</sub> O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Calibration Error %	Acceptable Range		
3.70	1.176	22.60	42.22	0.945	1.242	5.61	± 7%		

Sampler Operating Flow Rate							
Manometer "H₂O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Acceptable Range		
22.90	42.78	0.944	1.241	1.171	1.10 - 1.70		

#### Calculations:

Pressure mmHg (Pf) - "H<sub>2</sub>O \* 1.86832

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Calibration Error - (Sampler Flow-Orifice Flow)/Orifice Flow\*100



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor	John Kunke	el	
Operator	The Doe Run Company	Transfer Orifice	1882		
Location	Park Hills Network	Slope (Qa)	1.04094		
Station	Rivermines (Water Plant)	Intercept (Qa)	-0.00876		
Sampler	TSP	Temperature	31.8	°C	305.0 °K
Flow Controller	P4475	Station Pressure	30.08	"Hg	764.0 mmHg

Flow Rate Audit								
Transfer Orifice			San	npler		Calibration	Assantable	
Manometer "H₂O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Calibration Error %	Acceptable Range	
3.70	1.176	24.40	45.59	0.940	1.232	4.76	± 7%	

Sampler Operating Flow Rate							
Manometer "H₂O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Acceptable Range		
24.50	45.77	0.940	1.232	1.173	1.10 - 1.70		

#### Calculations:

Pressure mmHg (Pf) - "H2O \* 1.86832

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Calibration Error - (Sampler Flow-Orifice Flow)/Orifice Flow\*100



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor_	John Kunke	el		
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	Rivermines (Quarry)	Intercept (Qa)	-0.00876			
Sampler	#1 TSP	Temperature	31.8	_°C	305.0	°K
Flow Controller	P2940	Station Pressure	30.08	_"Hg	764.0	mmHg

ALC: UNITED IN	Flow Rate Audit								
Transfe	r Orifice		Sampler				Acceptable		
Manometer "H <sub>2</sub> O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Calibration Error %	Range		
3.60	1.160	23.70	44.28	0.942	1.240	6.90	± 7%		

Sampler Operating Flow Rate							
Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Acceptable Range		
23.20	43.35	0.943	1.241	1.155	1.10 - 1.70		

#### Calculations:

Pressure mmHg (Pf) - "H2O \* 1.86832

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Calibration Error - (Sampler Flow-Orifice Flow)/Orifice Flow\*100



3609 Mojave Court, Suite E Columbia, Missouri 65202 573-474-8110

Date	July 29, 2015	Auditor_	John Kunkel			
Operator	The Doe Run Company	Transfer Orifice	1882			
Location	Park Hills Network	Slope (Qa)	1.04094			
Station	Rivermines (above quarry)	Intercept (Qa)	-0.00876			
Sampler	#1 TSP	Temperature	31.8	°C	305.0	°K
Flow Controller	P2941	Station Pressure	30.08	"Hg	764.0	mmHg

	17 (40) (0:40 K 10:11-14 (4:40 K)	CONTROL OF THE	Flow Ra	ate Audit	rentante en de	The First Control	- 1 7 7年本。「おった - 1 7 9 527 7 78年
Transfe	Transfer Orifice Sam		Sampler		Calibration	Assentable	
Manometer "H <sub>2</sub> O	Flow Rate m³/min	Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Calibration Error %	Acceptable Range
3.70	1.176	23.20	43.35	0.943	1.243	5.70	± 7%

Sampler Operating Flow Rate						
Manometer "H <sub>2</sub> O	Pressure (Pf)	Press. Ratio (Po/Pa)	Flow Rate m³/min	Corrected Flow Rate	Acceptable Range	
22.90	42.78	0.944	1.244	1.173	1.10 - 1.70	

#### Calculations:

Pressure mmHg (Pf) - "H2O \* 1.86832

Pressure Ratio (Po/Pa) - 1-Pf/Pa

Orifice Flow Rate (Qa) - 1/Slope\*( Sqrt("H2O\*( Ta/Pa))-Intercept)

Sampler Flow Rate (Qa) - Taken from the look-up tables

Calibration Error - (Sampler Flow-Orifice Flow)/Orifice Flow\*100

## Calibration Orifice Certification Worksheet



TISCH ENVIRONMENTAL, INC. 145 SOUTH MIAMI AVE VILLAGE OF CLEVES, OH 45002 513.467.9000 877.263.7610 TOLL FREE 513.467.9009 FAX

#### ORIFICE TRANSFER STANDARD CERTIFICATION WORKSHEET TE-5028A

Date - Ja Operator		Rootsmeter Orifice I.I		833620 1882	Ta (K) - Pa (mm) -	292 765.81
PLATE	VOLUME	VOLUME	DIFF	DIFF	METER DIFF	ORFICE DIFF
OR VDC #	START (m3)	STOP (m3)	VOLUME (m3)	TIME (min)	(mm)	H2C (in.)
1 2 3 4 5	NA NA NA NA NA	NA NA NA NA NA	1.00 1.00 1.00 1.00	1.3360 1.0560 0.9570 0.8870 0.6670	4.3 6.8 8.2 9.5 16.5	1.50 2.50 3.00 3.50 6.00

#### DATA TABULATION

Vstd	(x axis) Qstd	(y axis)		Va	(x axis) Qa	(y axis)
1.0225 1.0191 1.0173 1.0155 1.0061	0.7654 0.9651 1.0630 1.1449 1.5084	1.2420 1.6034 1.7564 1.8972 2.4840		0.9943 0.9910 0.9892 0.9875 0.9784	0.7443 0.9385 1.0337 1.1133 1.4668	0.7563 0.9763 1.0695 1.1552 1.5125
Qstd slo	t (b) = ent (r) =	1.66236 -0.01438 0.99927		Qa slope intercept coefficie	t (b) = ent (r) =	1.04094 -0.00876 0.99927
y axis =	SQRT [H20 (1	Pa/760) (298/	 Ta)]	y axis =	SQRT [H20 (7	[a/Pa)]

#### CALCULATIONS

Vstd = Diff. Vol[(Pa-Diff. Hg)/760](298/Ta)
Qstd = Vstd/Time

Va = Diff Vol [(Pa-Diff Hg)/Pa]
Qa = Va/Time

For subsequent flow rate calculations:

Qstd =  $1/m\{ [SQRT (H2O (Pa/760) (298/Ta))] - b\}$ Qa =  $1/m\{ [SQRT H2O (Ta/Pa)] - b\}$ 

## Meteorological Sensor's Accuracy Checks

# Inquest Environmental, Inc. Wind Direction Sensor Performance Audit

Operator	The Doe Run Co.
Location	Big River
Station Name	Meteorological System
Technician	J Kunkel / M Kunkel
Sensor Mfg	RM Young
Sensor Model	Wind Monitor AQ
Serial Number	128618
Sensor Height	10.0 Meters

Date	07/29/2015
Start Time	10:30
Stop Time	11:30

Station Declination	1.1	Deg
Measured Angle	180.0	Deg
Corrected Angle	181.1	Deg
Alignment Error	-1.1	Deg

Vane	Data	Results		
Angle Degrees	Logger Degrees	Difference ± 3 Deg Limit	Total Error ± 5 Deg Limit	
0/360	1.1	1.1	0.0	
90	91.9	1.9	0.8	
180	181.1	1.1	0.0	
270	271.9	1.9	0.8	

Average Difference (Degrees)	1.5
Average Total Error (Degrees)	0.4

Audit Device	Wind Vane Alignment	Direction	
Туре	Pocket Transit	Vane Angle Fixture	
Mfg. Brunton		R.M. Young	
Model	5008	18212	
Serial No.	5080304492	None	

Comments: Wind direction was verified by determining the orientation of the sensor in respect to True North. This was measured using a tri-pod mounted transit aligned along the length of the sensor while locked from rotating.

A magnetic declination of 1.1 degrees was used to determine True North. The linearity of the sensor was determined by aligning the sensor to an indexed test fixture provided by the manufacturer. The four cardinal directions were verified using the fixture. No adjustments were made to the sensor.

## Wind Speed Sensor Performance Audit

Operator The Doe Run Co. Big River Location Station Name Meteorological System Auditor(s) J Kunkel / M Kunkel

Date 07/29/2015 10:30 Start Time Stop Time 11:30

Sensor Mfg RM Young Wind Monitor AQ Sensor Model Serial Number\_ 128618 Sensor Height 10.0 Meters

 $\pm (0.25 \text{ m/s} + 5\%)$ 

Audit Standard		DAS Re	DAS Response	
RPM	M/S	M/S	Difference	M/S
Zero	0.00	0.00	0.00	0.25
300	1.54	1.56	0.02	0.25
600	3.07	3.07	0.00	0.25
1200	6.14	6.15	0.01	0.56
1800	9.22	9.21	-0.01	0.71
3600	18.43	18.44	0.01	1.17
5400	27.65	27.63	-0.02	1.63
7200	36.86	36.85	-0.01	2.09
	Average		0.00	

	Average		0.00	
7200	36.86	36.85	-0.01	2.09
5400	27.65	27.63	-0.02	1.63
3600	18.43	18.44	0.01	1.17
1800	9.22	9.21	-0.01	0.71
1200	6.14	6.15	0.01	0.56
600	3.07	3.07	0.00	0.25

Audit Device	Anemometer Drive
Туре	Variable Speed
Mfg.	R.M. Young
Model	18801
Serial No.	CAO1631

Comments: Wind speed was verified using a variable speed anemometer drive. The propellor was removed from the sensor and the drive was connected using a flexible connector. The sensor was then rotated in the appropriate direction at several different speeds. Sensor responses were taken from the data logger. No adjustments were made to the sensor.

#### **Temperature Sensor Performance Audit**

Operator The Doe Run Co.

Location Big River

Station Name Meteorological System

Technician J Kunkel / M Kunkel

 Date
 07/29/2015

 Start Time
 10:30

 Stop Time
 11:30

#### **Sensor Information**

Sensor Mfg_	Climatronics
Sensor Model	NA
Serial Number	NA
Sensor Height	2 meters

Audit Device	Sensor		
°C	Data Logger °C	Difference °C	
0.5	0.5	0.0	
34.1	33.9	-0.2	
44.0	43.9	-0.1	
	Average	-0.1	

Note: The limit for each point is +/- 0.5 °C

Audit Device		
Туре	Digital Thermometer	
Mfg.	Control Company	
Model	15-077-8	
Serial No.	221381405	

Comments: The temperature is verified by co-locating the sensor with a certified digital thermometer. The verification is conducted at three levels using two water baths (iced and hot water) and the ambient temperature.

The sensor error was determined by comparing the sensor's data logger response to the display on the certified digital thermometer. No adjustments were made to the sensor.

## **Barometric Pressure Sensor Performance Audit**

Operator The Doe Run Co.

Location Big River

Station Name Meteorological System

Technician J Kunkel / M Kunkel

Date 07/29/2015
Start Time 10:30
Stop Time 11:30

 Sensor Mfg
 Setra

 Sensor Model
 276

 Serial Number
 2626447

	Data Logge	r Response	
Audit Device mm HG	BP mm HG	Difference mm HG	
741.20	744.60	3.40	

Note: Limit is +/- 7.5 mm HG.

Audit Device		
Туре	Digital Barometer	
Mfg.	AIR	
Model	AIR-HB-1A	
Serial No.	6G3745	

Comments: The barometric pressure is verified by co-locating the sensor with a certified digital barometer. The verification was conducted at one level after allowing the sensor and calibration device ample time to stabilize.

The sensor error was determined by comparing the sensor's data logger response to the display on the certified digital barometer. No adjustments were made to the sensor.

#### **Precipitation Gauge Performance Audit**

Operator The Doe Run Co
Location Big River
Station Name Meteorological System
Technician J Kunkel / M Kunkel

Date 07/29/2015
Start Time 10:30
Stop Time 11:30

 Sensor Mfg
 Texas Electronics

 Sensor Model
 TR525I

 Serial Number
 36611-805

 Diameter (inches)
 6.00

	Data Logger Response			
Audit Device  Known Tips	Gauge Tips	Difference %		
96.00	90.00	-6.25		

Note: Limit is +/- 10%.

Audit Device		
Туре	Graduated Beaker	
Mfg.	Texas Instruments	
Model	FC-525	
Serial No.	NA	

Comments: The precipitation gauge output was verified using a field calibration kit supplied by the manufacturer. The kit consists of a graduated beaker and a calibration funnel using a precision orifice at the water outlet.

Water was measured in the beaker and poured into the funnel while mounted on the gauge. The amount of precipitation recorded by the data logger was then compared to the known amount of water passing through the funnel. 100 tips equals one inch of rainfall. The gauge was cleaned and no adjustments were made.

**Meteorological Audit Devices Certifications** 

# BRUNTON OUTDOOR GROUP

CERTIFICATE OF CALIBRATION

**Equipment Owner** 

Name: Address:

Calibration traceable to the National institute of Standards and Technology in accordance with MIL-STD-45662A has been accomplish on the instrument listed below by comparison with standards maintained by the Brunton Outdoor Group. The accuracy and stability of all standards maintained by the Brunton Outdoor Group are traceable to national standards maintained by the National Institute of Standards and Technology in Washington, D.C. and Boulder, CO. Completed record of all work preformed is maintained by the Brunton Outdoor Group and is available for inspection upon request.
This unit has been calibrated to Lietz TM10E serial number 30937 traceable to N.B.S. Number 738227675 this fully Day 30 20 14.
Description Pocket Transit
Purchase Order25643 0329
Order Number <u>50 - 070367</u>
Model Number _ F - 3008
Serial Number
Calibration Date 7/30/14
Recalibration Date 7/30/15
Signed <u>Elis Myselles</u> 1/30/14
Quality Control Coordinator



#### CALIBRATION PROCEDURE 18801/18810 ANEMOMETER DRIVE

DWG: CP18801(A)

□ As Left

BY: TJT CHK: JC

REV: C101107 PAGE: 2 of 4 DATE: 10/11/07

W.C. GAS-12

## CERTIFICATE OF CALIBRATION AND TESTING

MODEL:

18801 (Comprised of Models 18820 Control Unit & 18830 Motor Assembly)

SERIAL NUMBER:

CA01631

R. M. Young Company certifies that the above equipment was inspected and calibrated prior to shipment in accordance with established manufacturing and testing procedures. Standards established by R.M. Young Company for calibrating the measuring and test equipment used in controlling product quality are traceable to the National Institute of Standards and Technology.

Nominal Motor Rpm	Output Frequency Hz (1)	Calculated Rpm (2)	Indicated Rpm (3)
600	320	600	600
1200	640	1200	1200
2400	1280	2A00	2400
4200	2240	4200	4200
6,000	3200	6000	6000
8,100	4320	8100	8100
9,900	5280	9900	9900

(1	Measured	at the	optical	encoder	output.
----	----------	--------	---------	---------	---------

Frequency output produces 32 pulses per revolution of motor shaft. (2)

Indicated on the Control Unit LCD display. (3)

*	Indicates	out of	to	lerance
	mondates	OUL OI	w	iei allice

No Calibration     No C	Adjustments Required	As Found	
Traceable frequency	meter used in calibration	Model: <u>DP5740</u>	SN: <u>4863</u>
Date of inspection Inspection Interval	16 Dec. 2014 One Year	Tested Ry	. 8,

Filename: CP18801(A).doc



## Calibration complies with ISO/IEC 17025, ANSI/NCSL Z540-1, and 9001



Cert. No.: 4000-6726396 Traceable® Certificate of Calibration for Digital Thermometer

Cust ID:Inquest Environmental Inc., 3609 Mojave Court, Suite E, Columbia, MO 65202 U.S.A. (RMA:995292) Instrument Identification:

Model Numbers: 15-077-8, 11705843 S/N: 221381404 Manufacturer: Control Company

Model: 15-077-7

S/N: 51202300

#### Standards/Equipment:

Description	Serial Number	Due Date	NIST Traceable Reference	
Temperature Calibration Bath TC-179 Thermistor Module Temperature Probe Temperature Calibration Bath TC-231	A45240 A17118 3039 A79341	3/03/16 4/02/16	1000371058 15A0P2S-20-1	
Thermistor Module Temperature Probe Temperature Calibration Bath TC-309	A27129 5202 B3A444	11/04/15 11/19/16	1000365407 6-CV9Y2-1-1	
Thermistor Module Temperature Probe	A27129 5267	11/04/15 11/19/16	1000365407 6-CV9Y0-1-1	

#### Certificate Information:

Technician: 68 Test Conditions:

Procedure: CAL-06

22.4°C

47.0 %RH 1012 mBar

Cal Date: 4/28/15

Due Date: 4/28/16

#### Calibration Data:

Unit(s)	Nominal	As Found	In Tol	Nominal	An Lat					
°C	0.004			Normial	As Left	In Tol	Min	Max	±U	TUR
	-0.001	0.011	Y	-0.001	-0.001	Y	-0.051	0.049	0.013	
°C	24.999	24.999	Y	24.999	25.000				0.013	3.8:1
°C	60.000			24.555	25.000	Y	24.949	25.049	0.014	3.6:1
	60.003	60.007	Y	60.003	60.001	Y	59.953	60.053	0.014	
°C	100.000	100.012	V	100.000			00.055	0.014	3.6:1	
10000	100.012	100.000	100.004	Y	99.950	100.050	0.014	3.6:1		

This Instrument was calibrated using Instruments Traceable to National Institute of Standards and Technology.

A Test Uncertainty Ratio of at least 4:1 is maintained unless otherwise stated and is calculated using the expanded measurement uncertainty. Uncertainty evaluation includes the instrument under test and is calculated in accordance with the ISO "Guide to the Expression of Uncertainty in Measurement" (GUM). The uncertainty represents an expanded uncertainty using a coverage factor k=2 herein relate only to the item calibrated. This certificate shall not be reproduced except in full, without written approval of Control Company.

Nominal=Standard's Reading; As Left=Instrument's Reading; In Tol=In Tolerance; Min/Max=Acceptance Range; ±U=Expanded Measurement Uncertainty; TUR=Test Uncertainty Ratio; Accuracy=±(Max-Min)/2; Min = As Left Nominal(Rounded) - Tolerance; Max = As Left Nominal(Rounded) + Tolerance, Date=MM/DD/YY

Aid Lodrigues
Nicol Rodriguez, Quality Manager

fali Aaron Judice, Technical Manager

#### Maintaining Accuracy:

In our opinion once calibrated your Digital Thermometer should maintain its accuracy. There is no exact way to determine how long calibration will be maintained. Digital Thermometers change little, if any at all, but can be affected by aging, temperature, shock, and contamination.

#### Recalibration:

For factory calibration and re-certification traceable to National Institute of Standards and Technology contact Control Company.

CONTROL COMPANY 4455 Rex Road Friendswood, TX 77546 USA Phone 281 482-1714 Fax 281 482-9448 service@control3.com www.control3.com

Control Company is an ISO 17025:2005 Calibration Laboratory Accredited by (A2LA) American Association for Laboratory Accreditation, Certificate No. 1750.01.

Control Company is ISO 9001:2008 Quality Certified by (DNV) Det Norske Veritas, Certificate No. CERT-01805-2006-AQ-HOU-RvA.

International Laboratory Accreditation Cooperation (ILAC) - Multilateral Recognition Arrangement (MRA).

Page 1 of 1

Traceable® is a registered trademark of Control Company

© 2009 Control Company



# HASS INSTRUMENT ....

6711 OLD BRANCH AVENUE • CAMP SPRINGS, MD 20748-6990 。 (301) 449-5454 • FAX (301) 449-5455

CALIBRATION REPORT

BAROMETER/ALTIMETER AIR Model AIR-HB-1A Serial No. 6G3745

TEST	TEST PRESSURE	DIGITAL READOUT	READOUT ERROR	CORRECTION REQUIRED
1	930.00	931.9	+1.9	-1.9
2	970.00	971.9	+1.9	-1.9
3	1010.00	1011.9	+1.9	-1.9
4	1050.00	1051.9	+1.9	-1.9
5	1011.97	1013.9	+1.9	-1.9

#### NOTES:

- 1. All data are in Millibars (hPA) and were taken at 70 F (21 C).
- 2. To correct the Digital Readout of the instrument, either algebraically add the CORRECTION REQUIRED to, or algebraically subtract the READOUT ERROR from, the readout shown on the instrument.
- 3. The TEST PRESSURE was generated using Type A-1 Barometer S/N 3327, and was approached in an increasing-pressure direction.
- 4. The TEST PRESSURE for TEST POINT 5 was ambient atmospheric pressure.
- 5. The BAROMETER/ALTIMETER was horizontal during the calibration.
- 6. The LCD screen of the BAROMETER/ALTIMETER has some trash in the center of the display, but it does not interfer with the readout.
- 7. Although the Digital Readout of the instrument can be adjusted to incorporate the average CORRECTION REQUIRED, this has not been done.

Calibration Date: 10 March 2015

By: Bernard J. Harr

Bernard I. Hass

(SEAL)





October 15, 2015

Amy Sanders The Doe Run Company P. O. Box 500 Viburnum, MO 65566

RE: Project: NPDES (RIVERMINES)

Pace Project No.: 60204550

# Dear Amy Sanders:

Enclosed are the analytical results for sample(s) received by the laboratory on October 08, 2015. The results relate only to the samples included in this report. Results reported herein conform to the most current TNI standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Jamie Church

jamie.church@pacelabs.com

**Project Manager** 

Jami Church

**Enclosures** 







#### **CERTIFICATIONS**

Project:

NPDES (RIVERMINES)

Pace Project No.:

60204550

#### Kansas Certification IDs

9608 Loiret Boulevard, Lenexa, KS 66219 WY STR Certification #: 2456.01 Arkansas Certification #: 15-016-0 Illinois Certification #: 003097 Iowa Certification #: 118 Kansas/NELAP Certification #: E-10116 Louisiana Certification #: 03055 Nevada Certification #: KS000212008A Oklahoma Certification #: 9205/9935 Texas Certification #: T104704407 Utah Certification #: KS00021





# **SAMPLE SUMMARY**

Project:

NPDES (RIVERMINES)

Pace Project No.: 60204550

Lab ID	Sample ID	Matrix	<b>Date Collected</b>	Date Received	
60204550001	38091 / RIVERMINES DOWNSTREAM	Water	10/07/15 11:13	10/08/15 08:50	
60204550002	38092 / RIVERMINES UPSTREAM	Water	10/07/15 11:37	10/08/15 08:50	
60204550003	38093 / RIVERMINES 001	Water	10/07/15 11:28	10/08/15 08:50	



# **SAMPLE ANALYTE COUNT**

Project:

NPDES (RIVERMINES)

Pace Project No.:

60204550

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
60204550001	38091 / RIVERMINES DOWNSTREAM	EPA 200.7	TDS	6	PASI-K
		EPA 200.7	JGP	3	PASI-K
		SM 2540D	CRS	1	PASI-K
		EPA 300.0	AJM	1	PASI-K
60204550002	38092 / RIVERMINES UPSTREAM	EPA 200.7	TDS	6	PASI-K
		EPA 200.7	JGP	3	PASI-K
		SM 2540D	CRS	1	PASI-K
		EPA 300.0	AJM	1	PASI-K
60204550003	38093 / RIVERMINES 001	EPA 200.7	TDS	3	PASI-K
		SM 2540D	CRS	1	PASI-K
		SM 2540F	CRS	1	PASI-K
		EPA 300.0	AJM	1	PASI-K



# **ANALYTICAL RESULTS**

Project:

NPDES (RIVERMINES)

Pace Project No.:

60204550

Sample: 38091 / RIVERMINES DOWNSTREAM

Date: 10/15/2015 02:45 PM

Lab ID: 60204550001

Collected: 10/07/15 11:13 Received: 10/08/15 08:50 Matrix: Water

2011110111271111									
Parameters	Results	Units	PQL	MDL	DF	Prepared	Analyzed	CAS No.	Qual
200.7 Metals, Total	Analytical	Method: EPA	A 200.7 Prepa	ration Meth	od: EF	PA 200.7			
Cadmium	8.4	ug/L	5.0	0.56	1	10/09/15 10:00	10/12/15 15:51	7440-43-9	
Calcium	166000	ug/L	100	5.2	1	10/09/15 10:00	10/12/15 15:51	7440-70-2	
Lead	10.1	ug/L	5.0	1.9	1	10/09/15 10:00	10/12/15 15:51	7439-92-1	
Magnesium	47200	ug/L	50.0	13.3	1	10/09/15 10:00	10/12/15 15:51	7439-95-4	
Total Hardness by 2340B	608000	ug/L	500		1	10/09/15 10:00	10/12/15 15:51		
Zinc	6290	ug/L	50.0	2.6	1	10/09/15 10:00	10/12/15 15:51	7440-66-6	
200.7 Metals, Dissolved (LF)	Analytical	Method: EPA	A 200.7 Prepa	aration Meth	od: EF	PA 200.7			
Cadmium, Dissolved	8.8	ug/L	5.0	0.56	1	10/13/15 14:40	10/14/15 15:40	7440-43-9	D9
ead, Dissolved	10.8	ug/L	5.0	1.9	1	10/13/15 14:40	10/14/15 15:40	7439-92-1	D9
Zinc, Dissolved	6740	ug/L	50.0	2.6	1	10/13/15 14:40	10/14/15 15:40	7440-66-6	
2540D Total Suspended Solids	Analytical	Method: SM	2540D						
Total Suspended Solids	6.0	mg/L	5.0	5.0	1		10/09/15 08:34		
300.0 IC Anions 28 Days	Analytical	Method: EPA	A 300.0						
Sulfate	402	mg/L	50.0	11.8	50		10/10/15 19:09	14808-79-8	



# **ANALYTICAL RESULTS**

Project:

NPDES (RIVERMINES)

Pace Project No.: 60204550

Sample: 38092 / RIVERMINES UPSTREAM

Date: 10/15/2015 02:45 PM

Lab ID: 60204550002

Collected: 10/07/15 11:37 Received: 10/08/15 08:50 Matrix: Water

Parameters	Results	Units	PQL	MDL	DF	Prepared	Analyzed	CAS No.	Qual
200.7 Metals, Total	Analytical	Method: EPA	A 200.7 Prepa	ration Meth	od: EF	PA 200.7			
Cadmium	< 0.56	ug/L	5.0	0.56	1	10/09/15 10:00	10/12/15 15:53	7440-43-9	
Calcium	47000	ug/L	100	5.2	1	10/09/15 10:00	10/12/15 15:53	7440-70-2	
Lead	<1.9	ug/L	5.0	1.9	1	10/09/15 10:00	10/12/15 15:53	7439-92-1	
Magnesium	28600	ug/L	50.0	13.3	1	10/09/15 10:00	10/12/15 15:53	7439-95-4	
Total Hardness by 2340B	235000	ug/L	500		1	10/09/15 10:00	10/12/15 15:53		
Zinc	5.8J	ug/L	50.0	2.6	1	10/09/15 10:00	10/12/15 15:53	7440-66-6	В
200.7 Metals, Dissolved (LF)	Analytical	Method: EP/	A 200.7 Prepa	ration Meth	od: EF	PA 200.7			
Cadmium, Dissolved	<0.56	ug/L	5.0	0.56	1	10/13/15 14:40	10/14/15 15:43	7440-43-9	
Lead, Dissolved	2.9J	ug/L	5.0	1.9	1	10/13/15 14:40	10/14/15 15:43	7439-92-1	
Zinc, Dissolved	5.8J	ug/L	50.0	2.6	1	10/13/15 14:40	10/14/15 15:43	7440-66-6	
2540D Total Suspended Solids	Analytical	Method: SM	2540D						
Total Suspended Solids	<5.0	mg/L	5.0	5.0	1		10/09/15 08:35		
300.0 IC Anions 28 Days	Analytical	Method: EPA	A 300.0						
Sulfate	34.7	mg/L	2.0	0.47	2		10/09/15 18:39	14808-79-8	

10/09/15 18:55 14808-79-8



# **ANALYTICAL RESULTS**

Project:

Sulfate

Date: 10/15/2015 02:45 PM

NPDES (RIVERMINES)

759

mg/L

Pace Project No.:

60204550

Sample: 38093 / RIVERMINES 001	Lab ID:	60204550003	Collected	: 10/07/1	5 11:28	Received: 10/	08/15 08:50 Ma	atrix: Water	
Parameters	Results	Units	PQL	MDL	DF	Prepared	Analyzed	CAS No.	Qual
200.7 Metals, Total	Analytical	Method: EPA 2	00.7 Prepar	ation Meth	nod: EP	A 200.7			
Cadmium	29.4	ug/L	5.0	0.56	1	10/09/15 10:00	10/12/15 16:00	7440-43-9	
Lead	63.9	ug/L	5.0	1.9	1	10/09/15 10:00	10/12/15 16:00	7439-92-1	
Zinc	21300	ug/L	50.0	2.6	1	10/09/15 10:00	10/12/15 16:00	7440-66-6	
2540D Total Suspended Solids	Analytical	Method: SM 25	540D						
Total Suspended Solids	<5.0	mg/L	5.0	5.0	1		10/09/15 08:35		
2540F Total Settleable Solids	Analytical	Method: SM 25	540F						
Total Settleable Solids	<0.20	mL/L/hr	0.20	0.20	1		10/09/15 08:05		
300.0 IC Anions 28 Days	Analytical	Method: EPA 3	0.00						

50.0

11.8



Project:

NPDES (RIVERMINES)

Pace Project No.:

60204550

QC Batch:

MPRP/33463

Analysis Method:

EPA 200.7

QC Batch Method:

EPA 200.7

Analysis Description:

200.7 Metals, Total

Associated Lab Samples: 60204550001, 60204550002, 60204550003

METHOD BLANK: 1647358

Matrix: Water

Date: 10/15/2015 02:45 PM

Associated Lab Samples: 60204550001, 60204550002, 60204550003

		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Cadmium	ug/L	<0.56	5.0	10/12/15 15:33	
Calcium	ug/L	9.5J	100	10/12/15 15:33	
Lead	ug/L	<1.9	5.0	10/12/15 15:33	
Magnesium	ug/L	<13.3	50.0	10/12/15 15:33	
Total Hardness by 2340B	ug/L	23.7J	500	10/12/15 15:33	
Zinc	ug/L	5.0J	50.0	10/12/15 15:33	

LABORATORY CONTROL SAMPLE:	1647360					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Cadmium	ug/L	1000	968	97	85-115	
Calcium	ug/L	10000	9900	99	85-115	
Lead	ug/L	1000	990	99	85-115	
Magnesium	ug/L	10000	9500	95	85-115	
Total Hardness by 2340B	ug/L		63800			
Zinc	ug/L	1000	961	96	85-115	

MATRIX SPIKE & MATRIX SP	IKE DUPLICA	TE: 16473	61		1647363							
	6	0204549001	MS Spike	MSD Spike	MS	MSD	MS	MSD	% Rec		Max	
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qual
Cadmium	ug/L	<0.56	1000	1000	988	1000	99	100	70-130	1	20	
Calcium	ug/L	98000	10000	10000	109000	108000	112	97	70-130	1	20	
Lead	ug/L	3.0J	1000	1000	984	1000	98	100	70-130	2	20	
Magnesium	ug/L	51700	10000	10000	62300	61600	107	100	70-130	1	20	
Total Hardness by 2340B	ug/L	457000			529000	523000				1		
Zinc	ug/L	121	1000	1000	1060	1080	94	96	70-130	2	20	

MATRIX SPIKE SAMPLE:	1647364	60204554002	Cnika	MC	MS	% Rec	
Parameter	Units	60204551002 Result	Spike Conc.	MS Result	% Rec	Limits	Qualifiers
Cadmium	ug/L	<0.56	1000	1000	100	70-130	
Calcium	ug/L	51800	10000	61800	101	70-130	
Lead	ug/L	<1.9	1000	1010	101	70-130	
Magnesium	ug/L	31700	10000	41800	101	70-130	
Total Hardness by 2340B	ug/L	260000		326000			
Zinc	ug/L	7.0J	1000	972	96	70-130	

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



Project:

NPDES (RIVERMINES)

Pace Project No.:

60204550

QC Batch:

MPRP/33508

Analysis Method:

EPA 200.7

QC Batch Method:

EPA 200.7

Analysis Description:

200.7 Metals, Dissolved

Associated Lab Samples:

METHOD BLANK: 1649804

Matrix: Water

Date: 10/15/2015 02:45 PM

Associated Lab Samples: 60204550001, 60204550002

60204550001, 60204550002

Parameter	Units	Blank Result	Reporting Limit	Analyzed	Qualifiers
Cadmium, Dissolved	ug/L	<0.56	5.0	10/14/15 15:19	
Lead, Dissolved	ug/L	<1.9	5.0	10/14/15 15:19	
Zinc, Dissolved	ug/L	<2.6	50.0	10/14/15 15:19	

LABORATORY CONTROL SAMPLE:	1649805					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Cadmium, Dissolved	ug/L	1000	982	98	85-115	
Lead, Dissolved	ug/L	1000	1030	103	85-115	
Zinc, Dissolved	ug/L	1000	996	100	85-115	

MATRIX SPIKE & MATRIX SP	PIKE DUPLICA	TE: 16498	06		1649807							
	60	0204550001	MS Spike	MSD Spike	MS	MSD	MS	MSD	% Rec		Max	
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qual
Cadmium, Dissolved	ug/L	8.8	1000	1000	1030	1030	102	102	70-130	0	20	
Lead, Dissolved	ug/L	10.8	1000	1000	1030	1030	102	102	70-130	0	20	
Zinc, Dissolved	ug/L	6740	1000	1000	7690	7560	95	82	70-130	2	20	

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





Project:

NPDES (RIVERMINES)

Pace Project No.:

60204550

QC Batch:

WET/57679

Analysis Method:

SM 2540D

QC Batch Method:

SM 2540D

Analysis Description:

Matrix: Water

2540D Total Suspended Solids

Associated Lab Samples:

Parameter

Parameter

60204550001, 60204550002, 60204550003

METHOD BLANK: 1647151 Associated Lab Samples:

60204550001, 60204550002, 60204550003

Blank Result

Reporting

Limit

Analyzed

Qualifiers

10

10

**Total Suspended Solids** 

Units mg/L

<5.0

5.0 10/09/15 08:27

SAMPLE DUPLICATE: 1647152

60204581001

Result

Dup Result

4

Qualifiers

**Total Suspended Solids** 

Units mg/L

mg/L

25.0

26.0

<5.0

**RPD** 

Max

SAMPLE DUPLICATE: 1647153

**Total Suspended Solids** 

Date: 10/15/2015 02:45 PM

Parameter

Units

60204518001 Result

Dup Result

**RPD** 

**RPD** 

Max **RPD** 

Qualifiers

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



Project:

NPDES (RIVERMINES)

Pace Project No.:

60204550

QC Batch:

WETA/36282

Analysis Method:

EPA 300.0

QC Batch Method:

EPA 300.0

Analysis Description:

300.0 IC Anions

Associated Lab Samples:

60204550001, 60204550002, 60204550003

Matrix: Water

METHOD BLANK: 1647186 Associated Lab Samples:

60204550001, 60204550002, 60204550003

Blank

Reporting

Parameter

Parameter

Parameter

Units Result Limit

Analyzed

Sulfate

mg/L

< 0.24

1.0 10/09/15 09:55

METHOD BLANK: 1648043

Associated Lab Samples:

Matrix: Water

60204550001, 60204550002, 60204550003

Blank Result Reporting Limit

Analyzed

Sulfate

Units mg/L

Units

mg/L

< 0.24

1.0 10/10/15 15:33 Qualifiers

Qualifiers

LABORATORY CONTROL SAMPLE: 1647187

Spike Conc.

LCS Result

LCS % Rec % Rec Limits

Qualifiers

LABORATORY CONTROL SAMPLE:

Parameter

Parameter

Parameter

1648044

Spike

LCS

Sulfate

Units

Conc. 5

5

Result

4.8

LCS % Rec % Rec Limits

Qualifiers

Sulfate

mg/L

ND

759

95

95

90-110

90-110

MATRIX SPIKE SAMPLE:

1647188

Units

mg/L

mg/L

60204521001 Result

Spike Conc.

500

250

4.8

MS Result

525

970

MS % Rec % Rec Limits

Qualifiers

Sulfate

Sulfate

60204550003

Spike

92

84

80-120

80-120

MATRIX SPIKE SAMPLE:

1647189

Units Result Conc.

MS Result

MS % Rec % Rec Limits

Qualifiers

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

This report shall not be reproduced, except in full, without the written consent of Pace Analytical Services, Inc..





# **QUALIFIERS**

Project:

NPDES (RIVERMINES)

Pace Project No.: 60

60204550

#### **DEFINITIONS**

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to dilution of the sample aliquot.

ND - Not Detected at or above adjusted reporting limit.

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PQL - Practical Quantitation Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine decomposes to and cannot be separated from Azobenzene using Method 8270. The result for each analyte is a combined concentration.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

**DUP - Sample Duplicate** 

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

#### LABORATORIES

PASI-K Pace Analytical Services - Kansas City

#### ANALYTE QUALIFIERS

Date: 10/15/2015 02:45 PM

B Analyte was detected in the associated method blank.

Dissolved result is greater than the total. Data is within laboratory control limits.



# **QUALITY CONTROL DATA CROSS REFERENCE TABLE**

Project:

NPDES (RIVERMINES)

Pace Project No.: 60204550

Date: 10/15/2015 02:45 PM

CP/24658
CD/24650
UF/24000
CP/24658
CP/24685
CP/24685



# Sample Condition Upon Receipt



Client Name: Oce Pun					Optional
Courier: FedEx → UPS □ VIA □ Clay □	PEX 🗆	EC		Pace ☐ Other ☐ Client ☐	Proj Due Date:
Tracking #: 7746 8134 8460	Pace Sh	ipping	Label U	Ised? Yes □ No 🕱	Proj Name:
Custody Seal on Cooler/Box Present: Yes ₱ No	□ Se	eals int	tact: Y	es∕t No □	
Packing Material: Bubble Wrap 🗷 Bubble Bag	gs 🗆		Foam [	□ None □ Other □	
Thermometer Used: CF+0.6 CF-70.5 Ty	pe of lo	e: Ø			ice, cooling process has begun.
Cooler Temperature: 1.3			(circle	Date and initia	Is of person examining
Temperature should be above freezing to 6°C				contents: th	V 10/8/15 1040
Chain of Custody present:	Yes	□No	□N/A	1.	
Chain of Custody filled out:	Yes	□No	□N/A	2.	
Chain of Custody relinquished:	1 Yes	□No	□n/A	3.	
Sampler name & signature on COC:	<b>Z</b> Yes	□No	□n/A	4.	
Samples arrived within holding time:	Yes	□No	□N/A	5.	
Short Hold Time analyses (<72hr):	XXVes	□No	□n/a	6. SoH. Sol.	
Rush Turn Around Time requested:	□Yes	No	□N/A	7.	
Sufficient volume:	Yes	□No	□N/A	8.	
Correct containers used:	<b>Z</b> Yes	□No	□n/A		
Pace containers used:	Yes	□No	□N/A	9.	
Containers intact:	<b>Z</b> Yes	□No	□N/A	10.	
Unpreserved 5035A soils frozen w/in 48hrs?	□Yes	□No	PN/A	11.	
Filtered volume received for dissolved tests?	□Yes	<b>≠</b> R₀	N/A	12.	
Sample labels match COC:	Yes	□No	□N/A		
Includes date/time/ID/analyses Matrix: Water Matrix: Water Matrix	ater			13.	
All containers needing preservation have been checked.	Yes	□No	PINIA		
All containers needing preservation are found to be in compliance with EPA recommendation.	17 Yes	□No	ØN/A	14.	
Exceptions: VOA, Coliform, O&G, WI-DRO (water)	Yes	□No			# of added servative
Trip Blank present:	□Yes	□No	N/A		
Pace Trip Blank lot # (if purchased):				15.	
Headspace in VOA vials ( >6mm):	□Yes	□No	DN/A		
				16.	
Project sampled in USDA Regulated Area:	□Yes	□No	<b>Z</b> N/A	17. List State:	
Additional labels attached to 5035A vials in the field?	□Yes	□No	□N/A	18.	
	OC to Cli	ent?	Y / I	N Field Data Required? Y	/ / N
Person Contacted: Da	ate/Time	e:			
Comments/ Resolution:					
				10/8/15	
Jane Church		-			
Project Manager Review:	-			Date:	

# CHAIN-OF-CUSTODY / Analytical Request Document The Chain-of-Custody is a LEGAL DOCUMENT. All relevant fields must be completed accurately

DOE RUN

Section		Sectio						ctio																	
								Invoice Information:										_						-	
			Report To: Army Sanders Copy To:					Attention: Amy Sanders Company Name: The Doe Run Company										PECIH ATORY	REGULATORY AGENCY Page:					1 of 1	
nudiess	PO 80X 500	ору г	·				Add	ress	y 140					Vibur					GROUND W	ATER	-			_1	
Email To	: asanders@doerun.com	urcha	se Or	rder No.:	***************************************		Paci	e Que	ote			~ 50	-	* 10001	*****	A. IV	100	C UST C	RCRA						
Phone:		Project	Nam	e. NDI	DES (Riv	ermines)		e Pro								-			110101	<i>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</i>	COC#:	2764			
	` ' '				DES (KIV	emmes)	Man	ager										Site Location	MO		4	Car	204	1550	
Reques	ed Due Date/TAT: 5 To 7 Days	Project	Num	ber:			Pac	e Pro	file #:									STATE:	manhad Asah		1	100	10		
		_	_	т —				_	_	_								Rec	uested Analy	SIS FIITER	BO (T/N	1			
	Section C Required Sample Information Valid Matrix Codes  MATRIX COI		ies 🗟 🖸 COLLECTED DATE/TIME				IME	E Bottles / Preservatives N										NNNNNN	NNNN	NNN	NN	NN	S		
			Ses (July of Septon)				SITE END /	٦,		П				-	T	T	1,	man and a second					SEMO Lab Project No./ Lab i.D.		
	MATRIX COD WATER WY WASTE WATER WAS	W 8 5 0		COMPOS			RAB							Glass H <sub>2</sub> SO <sub>4</sub>			H,SO.	*See Addi	tional Com	ments E	selow		1 5		
	SOIUSOLID SL	Valid	AB					COLLECTION	RS					T	*		T.						P		
		v ees)		1				S	CONTAINERS	Ved	Ped			Glass	3 2	텕	Amber Glass						10	. 1	
	SAMPLE ID	1						15	Ę	Ser	ser	8			-	5 2	3						ŭ		
	(A-Z, 0-9 / ,-)	8	Į w	1	1			10	Ó	e G	Pre-	S	9	Amber	1 6	13	pe						N.	-	
	Sample IDs MUST BE UNIQUE	3	1					P	유	5	5	les Se	ž.	A B	d	1 5	A	↓ An	alysis	rest	1		5		
*		ĺ €	믬	1				1 2	#	뒽	닡	L Unpreserved	립	물물	1 2	E	물				89 8 8 8		=	. 1	
ITEM		MATRIX CODE	SAMPLE TYPE	DATE	TIME	DATE	TIME (Military)	SAMPLE TEMP AT	Potal	250 mL Unpreserved	500 mL Unpreserved	1	250 mL Nitric	250 mL Amber	1000 ml Amber HCI	250	500 mL						,		
1	38091 ((\$(2w) 1(\$(3w)))	w		(mns/dd/yy)	(Military)	(mm/dd/yy) 10/07/15	(Military)	+"	2	-	1	-	1	2/0	1	+	N IN	CD-D, PB-D, ZN-D, HAR	D SOA CD T BI	LT TEE.T	7N.T	13335,13	vermines D	Councte	
2	(DISM)	1	1 6	-	+	10/07/15	1413	+	+	$\vdash$	-		-	+	+	+	+	COD, PBO, 2NO, HAR	0, 504, 00-1, F1	51, 1351,	214-1		germines L	Jownstr	
3	38092	w	TG		1	10/07/15	1137	+	12	+	1		1	+	+	+	+	CD-D, PB-D, ZN-D, HAR	D. SO4, CD-T, PI	B-T. TSS-T.	ZN-T		vermines L	Upstream	
4		+	1		1	1	1121	+	+					+	+	+	-								
5	38093 (BPIW) (BPZW) (GP3W).	w	WG		1	10/07/15	1128	1	3	1		1	1		1	T	1	1904, SS, TSS, CD-T, PE	B-T, ZN-T				Rivermines	s 001	
6								I	I						I	I									
7								L	L																
8		_	-					L	1						1	1	1								
9		_	1					1	1					-	-	+	-							$\overline{}$	
10		+	+		ļ			+	+	-		H	-	-	+	+	+							_	
11		+	+		-	-		+	+	-	H		-	-	-	+	-								
13		+	+	-	-		-	+	+	$\vdash$	H		-	+	+	+	+							-	
14		+	+	-	1	-		+	+	+	$\vdash$		-	+	+	+	+			-				-1	
15		+	+	1	1	<b> </b>		+	+	H	H		1	+	+	+	+								
16		+	+		<b>—</b>	<del>                                     </del>		t	+		Н		1	+	+	+	+								
17			1		1			T	T	T						1									
18								T	T																
19								I																	
20		_						1		L						_									
21		-	-		-			+	+	-				-	1	-									
22		+	+	_	-		-	+	+	-			-	-	+	+	+								
23		+	+	-	+	-		+	+	+			-	+	+	+	+					-			
25		+	+	1	-		-	+	+	+			-	+	+	+	+	<b> </b>							
26		+	+		1		<b>—</b>	+	+	+			-	+	+	+	-							-	
27		1	+		1			+	+	1			1	+	+	+	+								
28			1					+	1						1	1									
29								T		T					1							***************************************			
30			I					I	T								T								
Lanca, Armen	NAL COMMENTS					AFFILIATION	ON			DAT	E	0	TIME					TED BY AFFILIATION	DATE	CARRENCO	8/	AMPLE C	CONDITION	NS	
*200 7 To	al Recoverable and Dissolved Metals			LI	Hopkins	DRC			1	10/7/	15					54	M.	/ Ne / /a	19/6/15	850	1.3	Y	4	Y	
									+			-		-		1	- /				+	-			
				SAI	MPLER NA	AME AND	SIGNATU	RE													+	-	-	_	
				-				-		-	-	-					-				P S	1 38	Received on Ice (Y/N)	\$ 00 c	
					PRI	NT Name of	SAMPLE	ic:		1	2ar	rry h	lopi	kins	_	1	1				Temp in	DR in SU	200	Custody saled Cook (Y/N)	
					SIGI	NATURE of	SAMPLE	R	K	DI	>		1	K	24	1	-	DATE Signed	10/7/	15	10	ā.	80	Seal	